

(4257-01) ✓ *Staedtler Duo Markers - Blk* *

20808-2001

U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration		Form Approved OMB No. 44-R1387
MATERIAL SAFETY DATA SHEET		
Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)		

SECTION I		
MANUFACTURER'S NAME STAEDTLER MARS GmbH & Co.	62311550 ma d	EMERGENCY TELEPHONE NO. 0911 / 30 80 319
ADDRESS (Number, Street, City, State, and ZIP Code) Moosäckerstraße 3, D-8500 Nürnberg 90		
CHEMICAL NAME AND SYNONYMS	TRADE NAME AND SYNONYMS CALLIGRAPH DUO 3002 Black ink	
CHEMICAL FAMILY	FORMULA	

SECTION II - HAZARDOUS INGREDIENTS					
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Unit)	ALLOYS AND METALLIC COATINGS	%	TLV (Unit)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS Ethylene Glycohol	8	TWA vapor 50ppm	FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES				%	TLV (Unit)
none					

SECTION III - PHYSICAL DATA			
BOILING POINT (°F.)	N.D.	SPECIFIC GRAVITY (H ₂ O=1)	1.14
VAPOR PRESSURE (mm Hg.)	N.D.	PERCENT VOLATILE BY VOLUME (%)	85
VAPOR DENSITY (AIR=1)	N.D.	EVAPORATION RATE (—=1)	N.D.
SOLUBILITY IN WATER	soluble		
APPEARANCE AND ODOR	Black colored reiquid with low viscosity		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA			
FLASH POINT (Method used)	N.D.	FLAMMABLE LIMITS	N.A.
EXTINGUISHING MEDIA	N.D.		
SPECIAL FIRE FIGHTING PROCEDURES	N.D.		
UNUSUAL FIRE AND EXPLOSION HAZARDS	none		

PAGE (1)

(Continued on reverse side)

Form OSHA-20
Rev. May 72

SECTION V - HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE	N.D.
EFFECTS OF OVEREXPOSURE	N.D.
EMERGENCY AND FIRST AID PROCEDURES	
Eyes: Immediately flush with water enough and see a physician.	
Skin: Wash with soap water enough.	
Ingestion: Do not induce vomiting, see a phisician immediately.	

SECTION VI - REACTIVITY DATA			
STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	none
INCOMPATABILITY (Materials to avoid) N.D.			
HAZARDOUS DECOMPOSITION PRODUCTS N.D.			
HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	none

SECTION VII - SPILL OR LEAK PROCEDURES	
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED	
Wash with water and remove with cloth.	
WASTE DISPOSAL METHOD	
Waste disposal should be in accordance with existing federal, estate and local environmental regulations.	

SECTION VIII - SPECIAL PROTECTION INFORMATION			
RESPIRATORY PROTECTION (Specify type) N.D.			
VENTILATION	LOCAL EXHAUST	SPECIAL	
	MECHANICAL (General)	OTHER	
PROTECTIVE GLOVES	Rubber to prevent skin stain	EYE PROTECTION Goggles	
OTHER PROTECTIVE EQUIPMENT N.D.			

SECTION IX - SPECIAL PRECAUTIONS	
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	
Sotring: avoid high temperature or freezing.	
OTHER PRECAUTIONS none	