

27403-XXXX**TARA MATERIALS****MATERIAL SAFETY DATA SHEET**

Tara Cloth Sign and Banner Canvas

Tara Materials, Inc.
 322 Industrial Park Drive
 Lawrenceville, GA 30046
 770-963-5256

SECTION 1. CHEMICAL PRODUCT AND COMPANY IDENTIFICATION**PRODUCT NAME:** Tara Cloth Sign and Banner Canvas**PRODUCT USE:** Medium for signs, banners, and artist applications

MANUFACTURED BY: Tara Materials, Inc.
 322 Industrial Park Drive
 Lawrenceville, GA 30045

SECTION 2. COMPOSITION INFORMATION ON HAZARDOUS INGREDIENTS

<u>COMPONENT</u>	<u>%WT</u>	<u>CAS NO.</u>	<u>OSHA PEL</u>	<u>ACGIH TLV</u>
Crystalline silica	< 0.5	14808-60-7	0.1 mg/m ³ Resp	0.05mg/m ³ Resp
Ground Limestone Resp	15 – 30	1317-65-3	5 mg/m ³ Resp	2 mg/m ³
Titanium Dioxide Resp	5 – 15	131463-67-7	15 mg/m ³ Resp	10 mg/m ³

SECTION 3. HAZARDS IDENTIFICATION

DESCRIPTION: Sanding of these products may release dusts containing the hazardous components described above.

POTENTIAL HEALTH EFFECTS: Inhalation of airborne dust from sanding.
CAUTION: Dust can cause lung irritation.

SECTION 4. FIRST AID MEASURES

INHALATION: This product presents no inhalation hazard except when sanding or cutting. Perform these tasks in properly ventilated areas. Otherwise use an appropriate dust mask or respirator. If exposure occurs remove to fresh air. Consult a physician.

TARA MATERIALS**MATERIAL SAFETY DATA SHEET**

Tara Cloth Sign and Banner Canvas

Tara Materials, Inc.
322 Industrial Park Drive
Lawrenceville, GA 30046
770-963-5256

EYE CONTACT: Sanding or cutting these products may produce particles that could irritate the eyes. Flush eyes for 15 minutes and seek medical attention. Direct physical contact could cause injury by cutting or abrading the eyeball or surrounding tissues. Flush the eye(s) for 15 minutes if there seems to be particles still in the eye. Contact a physician to determine any other treatments necessary.

SKIN CONTACT: This product would not pose a skin contact hazard except as a result of direct contact resulting in cuts or abrasions. For minor injuries wash the affected area with mild soap and water. Treat as with other similar types of injury. For more serious injuries, or if unusual redness or swelling appears, seek medical attention.

INGESTION: Accidental ingestion of these products would be very unlikely. Although these products are considered non-hazardous, they should NEVER be ingested. Ingestion of moderate to large quantities could be harmful. Seek medical attention at once.

SECTION 5. FIRE FIGHTING MEASURES

FLASH POINT: None

EXPLOSIVE LIMITS: None

HAZARDOUS COMBUSTION PRODUCTS: Carbon monoxide, carbon dioxide, and other typical combustion by-products. Combustion may also produce an irritating dust due to the presence of calcium carbonate, and titanium dioxide. Do NOT inhale smoke from burning material.

AUTOIGNITION TEMPERATURE: >450° F

SECTION 6. ACCIDENTAL RELEASE MEASURES

Not Applicable

SECTION 7. HANDLING AND STORING

Store in a cool, dry place. Keep away from fire or other sources of ignition

TARA MATERIALS**MATERIAL SAFETY DATA SHEET**
Tara Cloth Sign and Banner CanvasTara Materials, Inc.
322 Industrial Park Drive
Lawrenceville, GA 30046
770-963-5256**SECTION 8. EXPOSURE CONTROLS / PERSONAL PROTECTION****ENGINEERING CONTROLS:** Use adequate ventilation when cutting or sanding.**RESPIRATORY PROTECTION:** None needed unless sanding or cutting the material. Use a suitable dust mask or respirator.**EYE PROTECTION:** None needed unless sanding or cutting. We recommend safety goggles designed for use with highly dusting materials.**SKIN PROTECTION:** None required unless suffering from acute dermatitis, hyper-sensitivity, or other skin ailments.**SECTION 9. PHYSICAL AND CHEMICAL PROPERTIES****APPEARANCE AND ODOR:** White coated canvas. None to very mild odor.

PHYSICAL STATE:	Solid	BOILING POINT:	None
pH:	Neutral	MELTING POINT:	None
VAPOR PRESSURE:	None	SOLUBILITY IN WATER:	Insoluble
VAPOR DENSITY:	Not Applicable	SPECIFIC GRAVITY:	> 1

SECTION 10. STABILITY AND REACTIVITY**STABILITY:** Stable**CONDITIONS TO AVOID:** Very high temperatures, open flames**INCOMPATIBILITY, MATERIALS TO AVOID:** Strong acids, caustics, strong oxidizers.**HAZARDOUS COMBUSTION PRODUCTS:** Carbon monoxide, carbon dioxide, dust**HAZARDOUS POLYMERIZATION:** Will Not Occur

TARA MATERIALS**MATERIAL SAFETY DATA SHEET**

Tara Cloth Sign and Banner Canvas

Tara Materials, Inc.
322 Industrial Park Drive
Lawrenceville, GA 30046
770-963-5256

SECTION 11. TOXICOLOGICAL INFORMATION

These products contain trace amounts of crystalline silica, which may cause cancer if inhaled. However, inhalation is unlikely except when cutting or sanding the material.

SECTION 12. DISPOSAL CONSIDERATIONS

No special disposal methods are needed. Observe all local, state, and federal regulations.

SECTION 13. TRANSPORTATION INFORMATION

Not Applicable

SECTION 14. REGULATORY INFORMATION

This product may contain extremely small amounts of one or more materials determined by the State of California to cause cancer, birth defects, or other reproductive harm. However, exposure to these components will only occur if the material is cut, sanded, or burned.

SECTION 15. MISCELLANEOUS INFORMATION

This MSDS was prepared based on the best available information from suppliers, government documents, and/or reference manuals.

DATE PREPARED: April 4, 2007

PREPARED BY: J.R. January